


测量

Sp1	72.8 °C
Sp2	73.9 °C
Sp3	76.6 °C
Sp4	76.8 °C
Sp5	77.3 °C
Sp6	74.1 °C
Sp7	73.6 °C
Sp8	71.7 °C
Sp9	68.4 °C
Sp10	68.3 °C
Sp11	75.1 °C
Sp12	77.2 °C
Sp13	77.8 °C
Sp14	76.6 °C
Sp15	76.4 °C
Sp16	75.0 °C
Sp17	72.2 °C
Sp18	66.5 °C
Sp19	65.5 °C
Sp20	67.9 °C
Sp21	74.8 °C
Sp22	77.4 °C
Sp23	77.3 °C
Sp24	76.5 °C
Sp25	76.5 °C
Sp26	74.6 °C
Sp27	72.7 °C
Sp28	65.5 °C
Sp29	67.4 °C
Sp30	71.7 °C
Sp31	74.3 °C
Sp32	75.3 °C
Sp33	75.5 °C
Sp34	75.1 °C
Sp35	75.7 °C
Sp36	74.0 °C
Sp37	72.9 °C
Sp38	63.3 °C
Sp39	73.9 °C
Sp40	75.4 °C
Sp41	76.1 °C
Sp42	76.8 °C
Sp43	77.1 °C
Sp44	74.8 °C
Sp45	72.9 °C
Sp46	71.6 °C
Sp47	67.2 °C
Sp48	64.6 °C
Sp49	73.5 °C

2019/6/11 11:45:45



FLIR0203.jpg

FLIR C2

720042994

2019/6/11 11:45:45



FLIR0203.jpg

FLIR C2

720042994